The second second

The state of the second second

ABSTRACT OF THE DISCLOSURE

A gap (34) for forming an excess thickness portion is provided between a pair of first dies (26, 27) and a intermediate portion (32) of the second die (24), and an excess thickness portion (35) is formed in bottom portions of the valve guide walls (28, 29) of valve guide walls.